

2019/06/21

HM D8.4 x30

2 mm

Fig.25: SEM image in the middle of the copper carrier




Fig. 26: EDX mapping in the middle of the copper carrier. Fluorine is clearly detected

